

Annexure –“A”PR no / dated **Supply of Hindusthan Make Pay loader(Model: 2021) Spares**

Sl. No	Material code	Material Description	Unit code	Stock in hand	Dues	Consumption rate	Item cat	Qty reqd
1.	300 002 026 018	Drive line assembly front (81022774)						01
2.	300 002 026 019	Drive line assembly rear (81022775)						01
3.	300 002 026 020	Oil seal front(81806515)						01
4.	300 002 026 021	Shoe Assembly(81048866)						08
5.	300 002 026 022	Drain cock(81000734)						05
6.	300 002 026 023	Valve assembly (Park brake) (81804990)						01
7.	300 002 026 024	Steering cylinder assy seal kit (81806969)						01
8.	300 002 026 025	Lift cylinder (81806968)						01
9.	300 002 026 026	Tilt Cylinder(81806967)						01
10.	300 002 026 027	Ball joint(89169495)						02
11.	300 002 026 028	Lock washer(3B4508)						02
12.	300 002 026 029	Nut(1B 4205)						02
13.	300 002 026 030	U.J.Kit(81804335)						02
14.	300 002 026 031	Bolt(0L0639)						20
15.	300 002 026 032	Lock washer(3B 4506)						20

16.	300 002 026 033	Nut(352713)						20
17.	300 002 026 034	Thrust washer (81017641)						04
18.	300 002 026 035	Thrust washer (81017638)						02
19.	300 002 026 036	Treadle valve repair kit(8180567)						01
20	300 002 026 037	Decluch valve repair kit(81800655)						01
21	300 002 026 038	UNloader valve repair kit(81803542)						01
22	300 002 026 039	Inversion valve repair kit(81800617)						01
23	300 002 026 040	Pressure protection on valve repair kit(81803543)						01
24	300 002 026 041	Relay emergency repair kit(81800608)						01
25	300 002 026 042	Orbitrol valve repair kit(81808065)						01
26	300 002 026 043	Steering sealkit(81806969)						02
27	300 002 026 044	Lift seal kit(81806900)						02
28	300 002 026 045	Bilt sealkit(81806358)						01